E	**************************************			; IBM					
0			2001/10/19 12:53	US-PGPU B; EPO; JPO; DERWENT	L7 and (zinc or zn)	182	18	BRS	8
0			2001/10/19 12:47	USPAT; US-PGPU B; EPO; JPO; DERWENT; IBM TDB	phosphor same (trench or hole)	1950	L7	BRS	7
0			2001/10/19 12:47	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	L5 and (zinc or zn)	25	16	BRS	6
0			2001/10/19 12:34	USPAT; US-PGPU B; EPO; JPO; DERWENT; IBM TDB	((zno or ((conductive or zinc) with oxide)) same trench) and (barrier or TiN or titanium)	279	L5	BRS	5
0			2001/10/19 12:03	₽ ∵□	((zno or (zinc with oxide)) same trench) and barrier	G	L4	BRS	.4
0			2001/10/19 11:57	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	((zno or (zinc adj oxide)) with trench) and barrier	2	L3	BRS	ω
0			2001/10/19 12:46	H ' G	Ll and (trench or hole)		L2 9	BRS	2
Ľ	Truncation Overflow. Return string from Server is: 5'41008'1		2001/10/19	HC	((zno or (zinc adj oxide)) near (insulat\$))	162	L1	BRS	н
rs	Error Definition	Comments	Time Stamp	DBs	Search Text	Hits	#	Туре	

							-
	2001/10/19	USPAT	("L14 not l15").PN.		L18 0	IS&R	18
	2001/10/19 13:46	USPAT	("5851849").PN.		L17 1	IS&R	17
	2001/10/19 13:44	USPAT	("6211073").PN.		L16 1	IS&R	16
	2001/10/19	USPAT; US-PGPU B; EPO; JPO; DERWENT; IBM TDB	trench and ((zinc adj ox\$) or (znwith o) or zno)	ω	L15 8	BRS	15
	2001/10/19 13:06	USPAT; US-PGPU B; EPO; JPO; DERWENT; IBM TDB	(trench or hole) and ((zinc ad) ox\$) or (zn with o) or zno)	2364 (L14 2	BRS	14
	2001/10/19	USPAT; US-PGPU B; EPO; JPO; DERWENT; IBM TDB	(trench or hole) and ((zinc adj ox\$) or (zn near o) or zno)	243	ш 2	BRS	13
	2001/10/19	USPAT; US-PGPU B; EPO; JPO; DERWENT; IBM TDB	barrier near (zinc or zn or zno)	ر و 9	L12 5	BRS	12 E
	2001/10/19 12:53	USPAT; US-PGPU B; EPO; JPO; DERWENT; IBM TDB	barrier with (zinc or zn or zno)	503	L11 1	BRS	11
	2001/10/19	USPAT; US-PGPU B; EPO; JPO; DERWENT; IBM TDB	barrier with (zinc or zn)	420	L10 1	BRS	10 B
	2001/10/19 12:48	USPAT; US-PGPU B; EPO; JPO; DERWENT; IBM TDB	and barrier	L8	L9 2	BRS	9
Comments				_		:	

	Type	#	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition
19	BRS	119	2281	L14 not 115	USPAT; US-PGPU B; EPO; JPO; DERWENT; IBM TDB	USPAT; US-PGPU B; EPO; 2001/10/19 JPO; DERWENT 13:47 ; IBM		
20	BRS	L20	383	L19 and barrier	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	USPAT; US-PGPU B; EPO; 2001/10/19 JPO; 13:57 DERWENT 13:57 ; IBM TDB		
21	IS&R	L21	1	("5383088").PN.	USPAT	2001/10/19 13:57		

8	7	6	ъ	4.	ω	2	H	
BRS	BRS	BRS	BRS	BRS	BRS	BRS	BRS	Type
В1	17	16 1	15	L4	13	12	Ľ.	L #
182	1950	25	279	ъ	2	Q	162	Hits
L7 and (zinc or zn)	phosphor same (trench or hole)	L5 and (zinc or zn)	((zno or ((conductive or zinc) with oxide)) same trench) and (barrier or TiN or titanium)	((zno or (zinc with oxide)) same trench) and barrier	((zno or (zinc adj oxide)) with trench) and barrier	L1 and (trench or hole)	((zno or (zinc adj oxide)) near (insulat\$))	Search Text
USPAT; US-PGPU B; EPO; JPO; DERWENT; IBM TDB	USPAT; US-PGPU B; EPO; JPO; DERWENT; IBM TDB	USPAT; US-PGPU B; EPO; JPO; DERWENT; IBM TDB	USPAT; US-PGPU B; EPO; JPO; DERWENT; IBM TDB	USPAT; US-PGPU B; EPO; JPO; DERWENT; IBM TDB	USPAT; US-PGPU B; EPO; JPO; DERWENT; IBM TDB	₽ ∵ □	USPAT; US-PGPU B; EPO; JPO; DERWENT; IBM TDB	DBs
2001/10/19	2001/10/19	2001/10/19 12:47	2001/10/19	2001/10/19 12:03	2001/10/19 11:57	2001/10/19 12:46	2001/10/19 11:55	Time Stamp
								Comments
							Truncation Overflow. Return string from Server is: 5`41008`1	Error Definition
0	0	0	0	0	0	0	Ъ	st

14

13

15

9


10

11

12

16 17 18

27	26	25	24	23	22	21	20	19	
BRS	BRS	BRS	BRS	BRS	BRS	IS&R	BRS	BRS	Туре
L27	L26	L25	L24	L23	122	L21	L20	L19	L #
4	10	0	16	14	ω	1	3 8 3	2281	Hits
438/622.ccls. and (zno or (zinc adj oxide))	257/758.ccls. and (zno or (zinc adj oxide))	257/760.ccls. and (zno or (zinc adj oxide))	257/751.ccls. and (zno or (zinc adj oxide))	257/763.ccls. and (zno or (zinc adj oxide))	257/767.ccls. and (zno or (zinc adj oxide))	("5383088").PN.	L19 and barrier	L14 not 115	Search Text
USPAT; US-PGPU B; EPO; JPO; DERWENT; IBM TDB	USPAT; US-PGPU B; EPO; JPO; DERWENT; IBM TDB	USPAT; US-PGPU B; EPO; JPO; DERWENT; IBM TDB	H C	4 . 4	USPAT; US-PGPU B; EPO; JPO; DERWENT; IBM TDB		USPAT; US-PGPU B; EPO; JPO; DERWENT; IBM; TDB	H ~ C	DBs
2001/10/19 15:10	2001/10/19 15:09	2001/10/19	2001/10/19 15:08	2001/10/19 14:15	2001/10/19 14:05	2001/10/19 13:57	2001/10/19 13:57	2001/10/19	Time Stamp
									Comments
									Error Definition
O	0	0	0	0	0	0	0	0	Erro



10/10/0

